

SECRET

Declassification Review by NGA/DoD

OUT 56212

S E C R E T 192201Z

1965 JUL 19 22 10Z

25X1

1. CAMERA B 122 WAS USED IN MISSION 8030 FLOWN ON 16 JULY 1965. 20 JUL 1965
PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: FINE EDGE FOG AND SMALL STATIC DISCHARGES ARE PRESENT ON THE OUTBOARD EDGE THROUGHOUT THE FILM. FAINT STATIC DISCHARGES ARE NOTED INTERMITTENTLY ON THE INBOARD EDGE. THERE IS A SMALL FLARED AREA ON THE INBOARD EDGE, 1.75" FROM THE CENTER OF THE DATA CHAMBER. A HEAT SPLICE IS POSITIONED BETWEEN FRAMES 316/317 AND FRAME 1744 CONTAINS A MANUFACTURER'S SPLICE.

C. 9L SIDE: BOTH FILM EDGES CONTAIN SMALL STATIC DISCHARGES. THE INBOARD EDGE ALSO EXHIBITS MINOR PROCESSING STREAKS IN FRAMES 240 TO 2515. FRAMES 206 TO 2515 CONTAIN A ROW OF MINUS DENSITY SPOTS 4.25" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM. A SIMILAR ROW IS PRESENT 1.50" FROM THE OUTBOARD EDGE IN FRAMES 355 TO 2515. IN BOTH CASES THE SPOTS ARE SPACED 1.55" APART. FRAMES 921 TO 2515 CONTAIN A ROW OF PLUS DENSITY SPOTS SPACED 1.65" APART AND RUNNING 2.45" FROM AND PARALLEL TO THE OUTBOARD EDGE. MANUFACTURER'S SPLICES ARE PRESENT IN FRAMES 980 AND 2237. NUMEROUS PINHOLES DEGRADE FRAMES 2237 TO 2240.

D. BOTH SIDES: THE METERING IS SLIGHTLY IRREGULAR AND RANGES

COPIES RECEIVED		
CV No.	Office	Act.
1	ENG	
	OS	
	ADMIN	
	SEC DR	
	IDS	
	IO	
	IS	
	ISB	
	ISD	
	ISG	
	ISL	
	ISN	
	ISX-4	
	ISD	
	ISCA-LO	
	ISCA-AP	

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1

FROM 0.35" TO 0.65". THE TITLED FRAMES ARE NUMBERED 0000 TO 2515.

D. THERE ARE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. THE CLOUD COVER IS APPROXIMATELY 20 PERCENT.

S E C R E T

/END OF MESSAGE/